

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**A1**  
**Target**  
**Property**

**USDA LIVESTOCK INSECT RESEARCH LAB**  
**2700 FREDERICKSBURG RD**  
**KERRVILLE, TX 78028**

**FINDS** **1011403140**  
**N/A**

**Site 1 of 3 in cluster A**

**Actual:**  
**1798 ft.**

FINDS:

Registry ID: 110035391812

Environmental Interest/Information System

Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

**A2**  
**Target**  
**Property**

**USDA AGRICULTURAL RESEARCH SERVICE**  
**FREDERICKSBURG RD**  
**KERRVILLE, TX 78028**

**SEMS-ARCHIVE** **1000187638**  
**CORRACTS** **TX6120514686**  
**RCRA NonGen / NLR**

**Site 2 of 3 in cluster A**

**Actual:**  
**1798 ft.**

SEMS Archive:

Site ID: 0604547  
EPA ID: TX6120514686  
Cong District: Not reported  
FIPS Code: 48265  
FF: Y  
NPL: Not on the NPL  
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information  
Latitude: 30.046667  
Longitude: -99.140000

SEMS Archive Detail:

Region: 06  
Site ID: 0604547  
EPA ID: TX6120514686  
Site Name: KNIPLING-BUSHLAND U.S. LIVESTOCK INSECT LABORATORY  
NPL: N  
FF: Y  
OU: 00  
Action Code: VS  
Action Name: ARCH SITE  
SEQ: 1  
Start Date: Not reported  
Finish Date: 1996-01-23 05:00:00  
Qual: Not reported  
Current Action Lead: EPA Perf In-Hse

Region: 06  
Site ID: 0604547  
EPA ID: TX6120514686  
Site Name: KNIPLING-BUSHLAND U.S. LIVESTOCK INSECT LABORATORY

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**USDA AGRICULTURAL RESEARCH SERVICE (Continued)**

**1000187638**

NPL: N  
FF: Y  
OU: 00  
Action Code: PA  
Action Name: PA  
SEQ: 1  
Start Date: Not reported  
Finish Date: 1996-01-23 05:00:00  
Qual: N  
Current Action Lead: Fed Fac

Region: 06  
Site ID: 0604547  
EPA ID: TX6120514686  
Site Name: KNIPLING-BUSHLAND U.S. LIVESTOCK INSECT LABORATORY  
NPL: N  
FF: Y  
OU: 00  
Action Code: DS  
Action Name: DISCVRY  
SEQ: 1  
Start Date: 1990-05-01 04:00:00  
Finish Date: 1990-05-01 04:00:00  
Qual: Not reported  
Current Action Lead: Fed Fac

**CORRACTS:**

EPA ID: TX6120514686  
EPA Region: 6  
Area Name: ENTIRE FACILITY  
Actual Date: 19920805  
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority  
NAICS Code(s): Not reported  
Original schedule date: Not reported  
Schedule end date: Not reported

**RCRA NonGen / NLR:**

Date form received by agency: 08/23/2001  
Facility name: USDA AGRICULTURAL RESEARCH SERVICE  
Facility address: FREDERICKSBURG RD  
KERRVILLE, TX 78028  
EPA ID: TX6120514686  
Mailing address: FREDERICKSBURG ROAD  
KERRVILLE, TX 78028  
Contact: SIDNEY KUNZ  
Contact address: FREDERICKSBURG ROAD  
KERRVILLE, TX 78028  
Contact country: US  
Contact telephone: 210-792-0308  
Contact email: Not reported  
EPA Region: 06  
Land type: Facility is not located on Indian land. Additional information is not known.  
Classification: Non-Generator  
Description: Handler: Non-Generators do not presently generate hazardous waste

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**USDA AGRICULTURAL RESEARCH SERVICE (Continued)**

**1000187638**

Owner/Operator Summary:

Owner/operator name: USDA AGRICULTURAL RESEARCH SERVICE  
Owner/operator address: FREDERICKSBURG ROAD  
KERRVILLE, TX 78028  
Owner/operator country: US  
Owner/operator telephone: 210-792-0308  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Not reported  
Owner/Operator Type: Owner  
Owner/Op start date: 08/23/2001  
Owner/Op end date: Not reported

Owner/operator name: USDA AGRICULTURAL RESEARCH SERVICE  
Owner/operator address: FREDERICKSBURG ROAD  
KERRVILLE, TX 78028  
Owner/operator country: US  
Owner/operator telephone: 210-792-0308  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Not reported  
Owner/Operator Type: Operator  
Owner/Op start date: 08/23/2001  
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
Mixed waste (haz. and radioactive): No  
Recycler of hazardous waste: No  
Transporter of hazardous waste: No  
Treater, storer or disposer of HW: No  
Underground injection activity: No  
On-site burner exemption: No  
Furnace exemption: No  
Used oil fuel burner: No  
Used oil processor: No  
Used oil refiner: No  
Used oil fuel marketer to burner: No  
Used oil Specification marketer: No  
Used oil transfer facility: No  
Used oil transporter: No

- . Waste code: D001
- . Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
- . Waste code: D002
- . Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**USDA AGRICULTURAL RESEARCH SERVICE (Continued)**

**1000187638**

CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Historical Generators:

Date form received by agency: 08/07/1980

Site name: US DEPT AGRI LIVESTOCK INSECTS

Classification: Conditionally Exempt Small Quantity Generator

- . Waste code: D001
- . Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
- . Waste code: U002
- . Waste name: ACETONE (I)
- . Waste code: U003
- . Waste name: ACETONITRILE (I,T)
- . Waste code: U006
- . Waste name: ACETYL CHLORIDE (C,R,T)
- . Waste code: U019
- . Waste name: BENZENE (I,T)
- . Waste code: U021
- . Waste name: BENZIDINE
- . Waste code: U031
- . Waste name: 1-BUTANOL (I)
- . Waste code: U044
- . Waste name: CHLOROFORM
- . Waste code: U080
- . Waste name: METHANE, DICHLORO-
- . Waste code: U112
- . Waste name: ACETIC ACID ETHYL ESTER (I)
- . Waste code: U115
- . Waste name: ETHYLENE OXIDE (I,T)
- . Waste code: U117
- . Waste name: ETHANE, 1,1'-OXYBIS-(I)
- . Waste code: U122
- . Waste name: FORMALDEHYDE
- . Waste code: U151

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**USDA AGRICULTURAL RESEARCH SERVICE (Continued)**

**1000187638**

. Waste name: MERCURY  
. Waste code: U154  
. Waste name: METHANOL (I)  
. Waste code: U159  
. Waste name: 2-BUTANONE (I,T)  
. Waste code: U188  
. Waste name: PHENOL  
. Waste code: U213  
. Waste name: FURAN, TETRAHYDRO-(I)  
. Waste code: U220  
. Waste name: BENZENE, METHYL-  
. Waste code: U224  
. Waste name: Not Defined  
. Waste code: U235  
. Waste name: 1-PROPANOL, 2,3-DIBROMO-, PHOSPHATE (3:1)  
. Waste code: U239  
. Waste name: BENZENE, DIMETHYL- (I,T)

**Corrective Action Summary:**

Event date: 08/05/1992  
Event: CA PRIORITIZATION-LOW CA PRIORITY

**Facility Has Received Notices of Violations:**

Regulation violated: Not reported  
Area of violation: TSD - General  
Date violation determined: 03/22/1988  
Date achieved compliance: 04/18/1988  
Violation lead agency: EPA  
Enforcement action: Not reported  
Enforcement action date: Not reported  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: Not reported  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: Not reported  
Area of violation: TSD - Closure/Post-Closure  
Date violation determined: 03/22/1988  
Date achieved compliance: 04/18/1988  
Violation lead agency: EPA  
Enforcement action: Not reported  
Enforcement action date: Not reported  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: Not reported  
Proposed penalty amount: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**USDA AGRICULTURAL RESEARCH SERVICE (Continued)**

**1000187638**

Final penalty amount: Not reported  
Paid penalty amount: Not reported

**Evaluation Action Summary:**

Evaluation date: 03/22/1988  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: TSD - Closure/Post-Closure  
Date achieved compliance: 04/18/1988  
Evaluation lead agency: EPA

Evaluation date: 03/22/1988  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: TSD - General  
Date achieved compliance: 04/18/1988  
Evaluation lead agency: EPA

**A3**  
**Target**  
**Property**  
**USDA-ARS-PS**  
**2700 FREDERICKSBURG RD**  
**KERRVILLE, TX 78028**

**ASBESTOS**  
**ENF**  
**S107646507**  
**N/A**

**Site 3 of 3 in cluster A**

**Actual:**  
**1798 ft.**

**ASBESTOS:**  
Date of inspection: 10/13/2017  
Reason for Inspection: Tammy Aviani  
Violation: Not reported  
Complaint Date: 10/13/2017  
Notification Number: 2017006901  
ASB Priority: Not reported  
PIF State: Not reported  
Detained: Not reported  
Product Name: Not reported  
Time Spent: Not reported  
Travel Time: Not reported  
Mileage: Not reported  
Reg: Not reported  
Init: Not reported  
Seq: Not reported  
Facility Type: Federal  
Inspector Name: Not reported  
Date Report Received: 10/05/2017  
Date Routed by Supervisor: Not reported  
Date Routed to PSQA: Not reported  
Date Reviewed by PSQA: Not reported  
Date Routed by Supervisor1: Not reported  
Date Rtd to Inspector Corrections: Not reported  
Date Rcvd Back: Not reported  
Date Rtd to Inspector Corrections2: Not reported  
Date Rcvd Back 2: Not reported  
Date Rtd to Inspector Corrections 3: Not reported  
Date Rcvd Back 3: Not reported  
Notification Status: Current  
Amendo: 1  
Notification Work Type: Abatement  
Notification Type: Amendment  
Work Type Flag: A  
Certification Statement Date: 10/05/2017  
Certification Statement Phone: 210-495-9009